

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

RECEIVED

July 9, 2009

A freeze brosen (34712)

Mr. James Thompson Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Assistant Council 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Steve Hepler

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Southwest Region Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 09-0338

ACHD Reference Number: 11385

600 Claus Plant USS Clairton Works

## Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler Plant Manager Clairton Works

Mark G. Table

## NOTICE OF PLANNED OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

USS Reference Number: 1. 09-0338 Termination

ACHD Reference Number: 11385

Date & Time of Outage: Date: 06/03/09 Time: 0700 hours 2.

- Company Name: U.S. Steel Corporation USS Clairton Works 3.
- Specific Equipment Involved or Affected: 600 Claus Plant 4.
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- Nature and cause of breakdown: During an approximate 2 3 week 7. period, the 600 Claus Plant will be unavailable for service to perform general maintenance.

The 600 Claus Unit is a redundant piece of equipment. processing for sulfur removal was handed off to the 400 Claus Unit. Sulfur Plant performance will not be affected. Sulfur emissions will not increase.

- Identification of Emissions: 8.
  - Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.) Α. The 400 Claus Plant will carry the full acid gas flow to the plant. No environmental impact is expected.
  - Toxic qualities of each type (including its qualities as an В. irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
  - Amount of each type emitted (or likely to be emitted). C. N/A
- Measures taken (or to be taken) to minimize length of breakdown 9. and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). Personnel, materials and equipment were on site prior to the start of the outage. The 400 Claus Plant carried the full acid gas flow to the plant.

10.	Facility	back	in	opera	tion	 Date:	07/07	7/09	Time:	1201	hours
	Signature Brya		****	h j			Dat		)/9 <u>/41</u>		

Bryan M. Kresak

Environmental Control Engineer Phone: 412-233-1468